

<b>Search Notes</b>	<b>Application/Control No.</b>	<b>Applicant(s)/Patent Under Reexamination</b>
	10807912	TSUDA ET AL.
	<b>Examiner</b>	<b>Art Unit</b>
	Chow, Yuk C	2609

### SEARCHED

<b>Class</b>	<b>Subclass</b>	<b>Date</b>	<b>Examiner</b>
345	156, 211,204,087	3/2/2008	YC
711	103	04/12/2007	YC
713	300	3/2/2008	YC

### SEARCH NOTES

<b>Search Notes</b>	<b>Date</b>	<b>Examiner</b>
Search help from Amare	04/12/2007	YC
Update search (determination ckt and restart power supply)	3/2/2008	YC
Update: restart a re-setup operation by drive setup circuit (via hardware instead of software of OS)	9/14/2008	YC
interference search	9/14/2008	YC

### INTERFERENCE SEARCH

<b>Class</b>	<b>Subclass</b>	<b>Date</b>	<b>Examiner</b>
Same as above	See all of above	9/14/2008	yc